



**ਦਫਤਰ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਉਪ ਮੰਡਲ, ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ,  
ਭਵਨ ਤੇ ਮਾਰਗ ਸਾਖਾ, ਮਲੇਰਕੋਟਲਾ**

ਵੱਲ

ਪ੍ਰਿੰਸੀਪਲ,  
ਡੀ.ਏ.ਵੀ. ਸੈਨਟੇਨਰੀ ਪਬਲਿਕ ਸਕੂਲ,  
ਮਲੇਰਕੋਟਲਾ।

*next due date*  
01/3/2025

ਨੰਬਰ **327** ਮਿਤੀ **22/07/24-24**  
ਵਿਸ਼ਾ: ਸਕੂਲ ਦੀ ਬਿਲਡਿੰਗ ਦੇ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਸਬੰਧੀ।  
ਹਵਾਲਾ: ਆਪ ਦਾ ਪੱਤਰ ਨੰ: DAV/MLK/2024-25 ਮਿਤੀ: 18-06-2024

ਉਪਰੋਕਤ ਵਿਸ਼ੇ ਅਤੇ ਹਵਾਲਾ ਅਧੀਨ ਪੱਤਰ ਦੇ ਸਬੰਧ ਵਿੱਚ ਲਿਖਿਆ ਜਾਂਦਾ ਹੈ ਕਿ ਇਸ ਉਪ ਮੰਡਲ ਦਫਤਰ ਦੇ ਜੂਨੀਅਰ ਇੰਜੀਨੀਅਰ ਸ੍ਰੀ ਬਲਪ੍ਰੀਤ ਸਿੰਘ ਵੱਲੋਂ ਆਪ ਜੀ ਦੇ ਸਕੂਲ ਦਾ ਨਿਰੀਖਣ ਕਰਨ ਉਪਰੰਤ ਰਿਪੋਰਟ ਕੀਤੀ ਗਈ ਹੈ ਕਿ ਬਿਲਡਿੰਗ ਸਾਲ 2024-25 (31-03-2025) ਤੱਕ ਬਾਰਰੋ ਵੇਖਣ ਵਿੱਚ ਸੇਫ ਜਾਪਦੀ ਹੈ। ਬਿਲਡਿੰਗ ਵਿੱਚੋਂ ਜੇਕਰ ਕੋਈ ਵੀ ਅਡੀਸ਼ਨਲ ਆਲਟਰੇਸ਼ਨ ਕਰਨੀ ਹੈ ਤਾਂ ਕਿਸੇ ਟੈਕਨੀਕਲ ਕੁਆਲੀਫਾਈਡ ਇੰਜੀਨੀਅਰ ਪਾਸੋਂ ਚੈੱਕ ਕਰਵਾ ਕੇ ਤਸਦੀਕ ਕਰਵਾਇਆ ਜਾਵੇ। ਜੇਕਰ ਹੜ੍ਹ, ਕੁਦਰਤੀ ਆਫਤ ਨਾਲ ਕੋਈ ਵੀ ਦੀਵਾਰ, ਨੀਹਾਂ ਬਰਿੰਦੀਆਂ ਹਨ ਤਾਂ ਉਸ ਬਾਰੇ ਵੀ ਟੈਕਨੀਕਲ ਕੁਆਲੀਫਾਈਡ ਇੰਜੀਨੀਅਰ ਪਾਸੋਂ ਚੈੱਕ ਕਰਾਉਣ, ਉਪਰੰਤ ਤਸਦੀਕ ਵੀ ਕਰਵਾਇਆ ਜਾਵੇ। ਇਸ ਦੀ ਇੰਸਪੈਕਸ਼ਨ ਫੀਸ ਜੀ.ਆਰ.ਨੰ: 675223 ਮਿਤੀ: 22-07-2024 ਰਾਹੀਂ 10,000/- ਰੁਪਏ ਜਮ੍ਹਾਂ ਕਰਵਾ ਲਈ ਗਈ ਹੈ। ਇਸ ਦੇ ਇਲਾਵਾ ਆਪ ਨੂੰ ਹਦਾਇਤ ਕੀਤੀ ਜਾਂਦੀ ਹੈ ਕਿ ਸਕੂਲ ਦਾ ਫਾਇਰ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਮਿਤੀ: 26/02/2025 ਤੱਕ ਖਤਮ ਹੋਣ ਉਪਰੰਤ ਰੀਨਿਊ ਕਰਵਾਕੇ ਇਸ ਦਫਤਰ ਜਮਾਂ ਕਰਵਾਉਣਾ ਯਕੀਨੀ ਬਣਾਇਆ ਜਾਵੇ, ਨਹੀਂ ਤਾਂ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਰੱਦ ਸਮਝਿਆ ਜਾਵੇਗਾ।

*[Signature]*

ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ  
ਪ੍ਰਾਂਤਕ ਉਪ ਮੰਡਲ ਲੇ:ਨਿ:ਵਿ:  
ਭ ਤੇ ਮ ਸਾਖਾ ਮਲੇਰਕੋਟਲਾ।

ਪਿੱਠ ਅੰਕਣ ਨੰਬਰ: ਮਿਤੀ:

ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਮੰਡਲ, ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ ਭ ਤੇ ਮ ਸਾਖਾ, ਮਲੇਰਕੋਟਲਾ ਜੀ ਨੂੰ ਆਪ ਜੀ ਦੇ ਪੱਤਰ ਨੰ: 1932 ਮਿਤੀ: 26-06-2024 ਦੇ ਸਬੰਧ ਵਿੱਚ ਸੂਚਨਾ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ ਜੀ।

ਨੱਥੀ/ਇੰਸਪੈਕਸ਼ਨ ਪ੍ਰੋਫਾਰਮਾ

*[Signature]*  
ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ  
ਪ੍ਰਾਂਤਕ ਉਪ ਮੰਡਲ ਲੇ:ਨਿ:ਵਿ:  
ਭ ਤੇ ਮ ਸਾਖਾ ਮਲੇਰਕੋਟਲਾ

## Building safety report

**NAME OF SCHOOL: DAV CENTENARY PUBLIC SCHOOL,  
MALERKOTLA.**

As per report of Sh. Balpreet Singh (Junior Engineer) on his visually inspection, the above mentioned school seems visually safe subject to the following observations and conditions:-

1. However, the Parameters to check the stability and safety of building such as Architectural Drawings, Bearing capacity, Foundation details, Structural drawings, Technical Specifications, Test reports of Material used and Quality control reports are not available.
2. In case any addition, alteration, expansion and modification to this building are required to be done, regarding this inspection of undersigned may be arranged and obtained a certificate after the completion from the undersigned.
3. In the case of building is affected by flood or if there is any settlement of walls foundation of roof etc. immediately inspection of the undersigned be arranged to check the stability and safety of the building.
4. A separate certificate regarding Fire Fighting should be obtained from the competent Authority.
5. A separate certificate regarding Electrical works should be obtained be from the competent Authority.
6. The owner of the building/ Management is fully responsible regarding safety of the building from all angles in spite of this report.
7. This report is for the covered area of the building as per Drawing submitted by the owner.
8. This report is not valid for legal purpose.
9. As per visually inspection as reported by the concerned Junior Engineer the above building may be used for normal use for One year up to 31/03/2025 subject to the above conditions.



**Sub-Divisional Engineer,  
Provl. Sub- Division,  
PWD B&R Malerkotla.**